

EE 8401 Electrical Machines - II.UNIT-3 Three phase Induction Motors

1. Explain the construction and operation of a 3 $\phi$  Induction Motor.


Notes:

Construction

The induction motor consists of two main parts.

1. Stator  $\rightarrow$  carries 3 $\phi$  stationary winding.
2. Rotor  $\rightarrow$  which rotates and is connected to the mechanical load through shaft.

Stator



Stator lamination

1. Stator has a laminated type of construction made up of stampings which are 0.4 to 0.5 mm thick.
2. The stampings are slotted on its periphery to carry stator winding.
3. The stampings are insulated from each other to keep the core loss minimum. The stampings stamped to built stator core.
4. The stampings are generally of silicon steel to keep the hysteresis loss minimum.
5. The slots on the periphery of the stator carries a three phase windings.



## Rotor


\* Rotor is placed inside the stator, also laminated in construction uses cast iron. The rotor conductors or winding is placed in the rotor slots.

Two types are construction are

→ Squirrel cage rotor and.

→ slip ring induction motor or wound ring I.M.

### 1. Squirrel cage I.M



The rotor core is cylindrical and slotted on its periphery. The rotor consists of uninsulated copper or aluminum bars called rotor conductors. Bars are placed in the slots.

The bars are permanently shorted at each end with the help of conducting copper ring called end ring.

The entire structure look like a cage. forming a closed electrical circuit. As the rotor are shorted entire rotor resistance is very very small.




The slots are not arranged parallel to the shaft axis but are skewed.

Advantages of skewing are,

1. A magnetic hum (ie) noise get reduced
2. It makes the motor operation smooth
3. Magnetic interlocking get reduced due to skewing.

Slip ring Rotor or Wound Rotor:-



In this type, rotor winding is exactly similar to the stator. The rotor carries a three phase star or delta connected distributed winding, wound for same no. of poles as that of stator.

The three ends of 3 $\phi$  windings are connected to the slip rings which is mounted on the same shaft. In this type of rotor



# Working Principle :-


Induction motor works on the principle of Electromagnetic

Induction.

When a 3 $\phi$  supply is given to the 3 $\phi$  stator winding a rotating magnetic field of constant magnitude is produced. The speed of the rotating magnetic field is synchronous speed  $N_s$ .

$$N_s = \frac{120f}{P}$$

$f \rightarrow$  frequency of supply  
 $P \rightarrow$  poles.




When supply is given the rotating magnetic field is produced in clockwise as shown in (a) fig.

At this instant rotor is stationary and stator flux is rotating. The RMF cuts the rotor conductors, so, whenever conductors cut the flux emf is induced in it. As rotor forms a closed circuit the induced emf circulates current through rotor called rotor current as shown in Fig (b).



Any current carrying conductor produces its own flux, so rotor produces its flux as shown in fig (c). The interaction of the flux due to RMF and rotor conductor is shown in fig (d).

On left of rotor conductor two fluxes interact with each other in same direction hence get added have high flux area.



On right side two fluxes cancel each other to produce low flux area so rotor conductor experiences a force from left to right.

All the conductor experiences a force as well and rotor experiences a torque and starts rotating.

$N_s \rightarrow$  speed of rotating RMF

$N \rightarrow$  speed of rotor i.e. rotor speed,

$N_s - N \rightarrow$  Relative speed between two rotating magnetic field and the rotor conductor.

2. Develop an equivalent circuit for 3 $\phi$  I.M. state the difference between exact and approximate equivalent circuits.



An 3φ Induction Motor the stator acts a primary & rotor acts as a secondary. when I.M. is treated as a transformer

If  $E_1 \rightarrow$  Induced voltage in stator per phase

$E_2 \rightarrow$  Rotor induced emf per phase on stand still

$$k = \frac{E_2}{E_1}$$

$V_1 \rightarrow$  applied voltage per phase to stator.

$E_{2r} \rightarrow$  Rotor induced emf in running condition


$R_2 \Rightarrow$  rotor resistance per phase

$X_{2r} \rightarrow$  rotor reactance per phase in running condition

$R_1 \rightarrow$  stator resistance per phase

$X_1 \rightarrow$  stator reactance per phase.

When supply is given  $E_1$  emf will induced in the stator and by mutual induction  $E_2$  will be induced in the rotor at stand still. In running condition the induced emf in rotor becomes  $E_{2r}$  which is  $sE_2$ .



$I_c \rightarrow$  Active component

$I_m \rightarrow$  magnetizing component


$$\bar{I}_0 = \bar{I}_c + \bar{I}_m$$

$$R_0 = \frac{V_1}{I_c}$$

$$X_0 = \frac{V_1}{I_m}$$



Equivalent ckt can be represented as.



$I_{2r}$  = rotor current in running condition

$$I_{2r} = \frac{E_{2r}}{Z_{2r}} = \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}}$$

Representation of rotor impedance

$$I_{2r} = \frac{sE_2}{\sqrt{R_2^2 + (sX_2)^2}} = \frac{E_2}{\sqrt{\left(\frac{R_2}{s}\right)^2 + X_2^2}}$$

taking  $R_2/s$  as;


$$\frac{R_2}{s} = R_2 + \frac{R_2}{s} - R_2$$

$$\frac{R_2}{s} = R_2 + R_2 \left[ \frac{1}{s} - 1 \right] \Rightarrow R_2 + R_2 \left[ \frac{1-s}{s} \right]$$

$R_2$  → rotor resistance represents copper loss.

$R_2 [1-s]/s$  represents load resistance  $R_L$ .

∴ equivalent circuit can be shown as,





Equivalent circuit referred to stator


$$E_2' = E_2/k, \quad I_{2r}' = k I_{2r}$$

$$X_2' = X_2/k^2, \quad R_2' = R_2/k^2$$

$$R_L' = \frac{R_L}{k^2} = R_2' \left[ \frac{1-s}{s} \right]$$


So equivalent circuit referred to stator

shown as




Approximate equivalent circuit

Approximate equivalent circuit can be drawn by shifting the exciting circuit to the left of  $R_1 + X_1$



$$R_{ie} = R_1 + R_2' \Rightarrow \text{equivalent resistance referred to stator} = R_1 + R_2/k^2$$

$$X_{ie} = X_1 + X_2' \rightarrow \text{equivalent reactance referred to stator} = X_1 + X_2/k^2$$



$$I_1 = I_0 + I_{2r}'$$

$$I_0 = I_c + I_m$$




Q3

Draw the torque slip characteristics of an induction motor for varying frequency, stator voltage and rotor resistance.

(i) Effect of change in rotor resistance on Torque:-

In slip ring induction motor external resistance can be added in the rotor.

$R_2$  = rotor resistance per phase



$$\text{Torque } T \propto \frac{s E_2^2 R_2}{R_2^2 + (s X_2)^2}$$

$R_2'$  = New rotor resistance

$$T' \propto \frac{s E_2^2 R_2'}{R_2'^2 + (s X_2)^2}$$

$s=1$ ,  $R_2$  and  $R_2'$  can be written as

$$T_{st} \propto \frac{E_2^2 R_2}{R_2^2 + X_2^2}$$

$$T_{st}' \propto \frac{E_2^2 R_2'}{R_2'^2 + X_2^2}$$

Max Torque,  $T_m \propto \frac{E_2^2}{2 X_2}$



For  $R_2$ ,  $S_m = \frac{R_2}{X_2}$  where  $T_m$  occurs

$$S'_m = \frac{R_2'}{X_2}$$

As  $R_2' > R_2$  the slip  $S'_m > S_m$  Due to this we get a new torque-slip characteristics for rotor resistance  $R_2'$

This new characteristics is parallel to the characteristics for  $R_2$  with same  $T_m$  but occurring at  $S'_m$

It is observed with increase in resistance the max torque remain the same and the starting torque can be increased.

### Effect of change in Voltage and frequency

Case 1. Halving the applied voltage, keeping frequency constant

When the motor is running with slip  $s$ , the torque

$$T_s = \frac{k_s E_2^2 R_2}{R_2^2 + (sX_2)^2}$$



Now standstill e.m.f.  $E_2$  is proportional to the supply voltage


$$T = \frac{k' s V^2 R_2}{R_2^2 + (sX_2)^2} \quad \text{where } k' \text{ is another constant}$$

On full load, slip  $s$  is very small hence  $(sX_2)^2 \ll R_2^2$ ,

$$T = \frac{k' s V^2 R_2}{R_2^2} = \frac{k' s V^2}{R_2}$$

$$T \propto s V^2$$

If the supply is made half then torque will reduce by the factor  $(\frac{1}{4})$ , in the running conditions.



The slip at which  $T_{max}$  occurs remains same but the value of  $T_{max}$  reduces. as show in fig.

Case 2: Halving both the applied voltage and frequency

For an induction motor, the air gap flux is given by

$$\phi_g = \frac{1}{4.44 k_1 T_{ph}} \left( \frac{V}{f} \right)$$




# Circle Diagram of 3φ Induction Motor

The circle diagram of a 3φ induction motor is the graphical representation of the equivalent circuit. All the information that can be obtained from the equivalent circuit can also be obtained from the circle diagram.

Following test data required to draw circle diagram.

## No load Test

Open ckt test is conducted on the 3φ I.M. to determine No. load current  $I_0$ , power factor  $\cos \phi_0$ , windage and friction losses.



No. load copper losses ( $I_0^2 R$ ) no load power Input  $P_0$

$$W_0 = \sqrt{3} V_L I_0 \cos \phi_0$$

$$\cos \phi_0 = \frac{W_0}{\sqrt{3} V_L I_0}$$

$$I_w = I_0 \cos \phi_0$$

$$I_\mu = I_0 \sin \phi_0$$

$$R_0 = \frac{V_L / \sqrt{3}}{I_0}$$

$$X_0 = \frac{V_L / \sqrt{3}}{I_\mu}$$



## Blocked Rotor Test



This test is conducted to determine the short circuit current ( $I_{sc}$ ) with rated current drawn by the motor, power factor on short circuit & equivalent resistance ( $R_0$ ) & reactance  $X_0$ , referred to stator side.

$$W_{sc} = \sqrt{3} V_s I_s \cos \phi_{sc}$$

$$\cos \phi_{sc} = \frac{W_{sc}}{V_s I_s}$$

$$I_{SN} = \left( \frac{V}{V_s} \right)^2 I_s \quad \text{(Current at normal voltage)}$$


$$W_{SN} = \frac{V}{V_s} \times W_s \quad \text{(Power at normal voltage)}$$



## ③ Stator Resistance Test

Using this test resistance of the stator winding resistance is determined.

The total resistance of the two winding is measured & value is divided by 2. From the resistance value is multiplied by 1.25 to obtain actual resistance.









Now draw  $OX$  and  $AR$  perpendicular to the phasor  $V$ . Draw the perpendicular bisector of  $AB$  such that it meets  $AR$  at  $C$ .

With  $C$  as centre and radius  $AC$  draw a circle  $OX$ . By taking the ratio of rotor resistance per phase ( $r_2$ ) referred to stator to that of effective stator resistance per phase ( $r_1$ ) divide the line  $BE$  at  $F$ . i.e.,

$$\frac{BF}{FE} = \frac{r_2}{r_1}$$

Join the point  $A$  and  $F$  where  $AF$

represents the torque line. The circle diagram of a 3 $\phi$  induction motor along with its specifications is shown.

Specifications

- $AB$  = Output line
- $AF$  = Torque line
- $ab$  = Maximum power output
- $cd$  = Maximum torque
- $ED = AH = gh$  = Fixed loss.

Now, for any operating points (i.e) when the motor is running, taking current as  $OI$  and by drawing a perpendicular  $Ih$  on  $OX$ , the entire performance of the motor can be obtained.

- $OI$  =  $I$  per phase current
- $eI$  = Power output
- $cf$  = rotor ohmic loss
- $fg$  = stator ohmic loss
- $gh$  = friction windage and core loss
- $Ih$  = power input



$$\frac{I_f}{\omega_s} = \text{Torque}, \quad \frac{s}{I_f} = \text{slip.}$$

$$\frac{I_h}{O_h} = \text{power factor} + \frac{eI}{I_h} = \text{Efficiency}$$


Hence the characteristics of an induction motor can be determined theoretically from its circle diagram by using the data from no-load, blocked rotor & stator resistance tests.

5. Explain the speed torque characteristics of double cage induction motor with a neat diagram.

Construction of Double Cage Rotor:-

In double cage rotor induction motor, its stator is similar to that of ordinary induction motor.

The only difference is in the rotor construction. The rotor of double cage induction motor is constructed by using two sets of squirrel cage windings which are provided on the rotor separated by narrow slit or construction.



Double cage rotor construction

The upper cage or the starting cage which is very close to the air gap is made of high resistivity materials such as aluminium, bronze etc.



Lower cage made up of copper. The cross section of upper cage is smaller than the lower cage and hence the resistance of upper cage is higher than that of lower cage. The diagram is shown in fig.

Double cage induction motor has two cages on the same rotor, a high resistance and low reactance bar on outer cage and low resistance and high reactance bar on inner cage.

The frequency of rotor current is high due to large slip, which is nearly equal to supply frequency. The current supplied to inner cages of rotor will be inversely proportional to their impedances.


Thus the current in the inner cage is small but the outer cage current is enclosed coils has a high resistance. This gives good starting torque.

When the speed of the motor is increased the frequency of the rotor current gets decreased. Thus the leakage reactance of inner cage is reduced when the motor is running at full speed.

Therefore the reactance of both of the cages become too small and the current is divided in the ratio of resistances.



## Torque speed characteristics.



The figure shows the torque speed characteristics of double cage induction motor. The outer cage provides a high starting torque whereas the inner cage helps in obtaining the sufficient speed at the normal running condition.

Here both the characteristics combined to provide an excellent torque-speed characteristics curve.

Due to this characteristics double cage induction motor is also known as low starting current, high starting torque, low slip motor.

6. A 3 phase induction motor has a starting torque of 100% and a maximum torque of 200% of its full load torque. Determine



- (i) slip at which maximum torque occurs
- (ii) full load slip
- (iii) Rotor current at starting in per cent of full

Solution

Given  $T_{st} = 100\% \cdot T_{FL}$ ,

$T_m = 200\% \cdot T_{FL}$ .

$$\frac{T_{st}}{T_m} = \frac{T_{FL}}{2T_{FL}} = \frac{1}{2} = 0.5$$

$$\frac{T_{st}}{T_m} = \frac{2s_m^2}{s_m(1+s_m^2)} = \frac{2s_m}{1+s_m^2} = 0.5$$

$$\Rightarrow 0.5s_m^2 - 2s_m + 0.5 = 0$$

$$\frac{-b \pm \sqrt{b^2 - 4ac}}{2a} \Rightarrow \frac{+2 \pm \sqrt{2^2 - 4 \times 0.5 \times 0.5}}{2 \times 0.5}$$

$$s_m = 3.76, 0.2679$$

(i) slip at which  $T_m$  occurs  $s_m = 0.2679$

= 26.79%



$$(ii) \frac{T_{FL}}{T_m} = \frac{1}{2} = 0.5$$

$$\frac{T_{FL}}{T_m} = \frac{2a sf}{a^2 + sf^2}$$

$$a = s_m = \frac{R_2}{X_2}$$

$$s_m = \frac{R_2}{X_2} = 0.2679$$

$$\Rightarrow \frac{2 \times 0.2679 \times sf}{(0.2679)^2 + sf^2} = 0.5$$

$$0.5 sf^2 - 0.5358 sf + 0.03588 = 0$$

$$\frac{-b \pm \sqrt{b^2 - 4ac}}{2a}$$

$$= \frac{+0.5358 \pm \sqrt{(0.5358)^2 - 4 \times 0.5 \times 0.03588}}{2 \times 0.5}$$

$$sf = 0.0717, 0.99$$

$$\therefore \text{full load slip} = 0.0717 \text{ i.e. } 7.17\%$$

$$(iii) T \propto \frac{I^2}{s}$$

$$\frac{T_{st}}{T_{FL}} = \frac{I_{st}^2}{I_{FL}^2} \times \frac{sf}{s}$$

$$\because s=1, \text{ at start}$$

$$T_{st} = T_{FL}$$



$$1 = \frac{I_{st}^2}{I_{FL}^2} \times 0.9717.$$

$$\text{i.e. } \frac{I_{st}}{I_{FL}} = 3.7345$$

$$I_{st} = 3.7345 I_{FL}$$

So motor current at start is 3.7345 times full load motor current.

7. The real power input to a 415 V 50 Hz 6 pole 3 $\phi$  induction motor running at 970 rpm. is 41 kW. The input power factor is 0.9. The stator losses amount to 1.1 kW and the mechanical losses amount to 1.2 kW. Calculate the  
 (i) line current, (ii) slip, (iii) motor copper loss, (iv) mechanical power output (v) efficiency.

Solution:

Given :-  $V_L = 415 \text{ V}$ ,  $f = 50 \text{ Hz}$ ,  $P = 6$ ,  $N = 970 \text{ rpm}$ .  
 $P_{in} = 41 \text{ kW}$ ,  $\cos \phi = 0.9$ , stator losses = 1.1 kW,  
 Mech. loss = 1.2 kW.

To find:  $I_L = ?$ ,  $s = ?$ ,  $P_{cu} = ?$ ,  $P_{out} = ?$ ,  $\eta = ?$ .

$$P_{in} = \sqrt{3} V_L I_L \cos \phi.$$

$$I_L = \frac{P_{in}}{\sqrt{3} V_L \cos \phi} = \frac{41 \times 10^3}{\sqrt{3} \times 415 \times 0.9} = 63.377 \text{ A}.$$

$$I_L = 63.377 \text{ A}$$



(ii)

$$N_s = \frac{120f}{p} = \frac{120 \times 50}{6} = 1000 \text{ rpm.}$$

$$s = \frac{N_s - N}{N_s} = \frac{1000 - 970}{1000} \Rightarrow 0.03$$

$$s = 0.03 \text{ or } 3\%$$

(iii)

$$\text{Rotor input} = P_{in} - \text{stator losses} \\ = (44 \times 10^3) - (10.1 \times 10^3)$$

$$P_r = 33.9 \text{ kW}$$

$$P_{cu} = s \times P_r \rightarrow \text{rotor input.}$$

$$= 0.03 \times 33.9 \times 10^3$$

$$P_{cu} = 1.197 \text{ kW} \quad \text{Rotor copper loss}$$

(iv) Mech. power.

$$\frac{P_{cu}}{P_m} = \frac{s}{1-s} \Rightarrow P_m = \frac{P_{cu} [1-s]}{s}$$

$$= \frac{1.197 \times 10^3 [1 - 0.03]}{0.03} = 38.703 \text{ kW}$$

$$P_m \text{ output} = P_{out} = P_m - \text{Mech. loss.}$$

$$\Rightarrow (38.703 \times 10^3) - (1.2 \times 10^3)$$

$$P_{out} = 37.503 \text{ kW}$$

(v)

Efficiency

$$\eta = \frac{P_{out} \times 100}{P_{in}}$$

$$= \frac{37.503 \times 10^3}{44 \times 10^3} \times 100$$

$$\eta = 91.47\%$$